








**Термопреобразователи к измерителю температуры ИТ 5 - Т**

Рисунок, Т раб.	Тип	d, мм	l, мм									
			60	80	100	120	200	300	400	600	800	
<b>ТКЖ1 (погружной)</b>												
	50М	2	-	+	+	-	-	-	-	-	-	
		4	-	-	-	+	+	+	+	+	+	
	100П	4	-	-	-	+	+	+	+		+	
		5	-	-	-	-	-	-	-	+	+	
Тип	Т раб.											
50М	-50... 160°C											
100П	-30... 160°C											
Pt100	-30... 160°C		Pt100	2	-	+	+	-	-	-	-	-
				4	-	-	-	+	+	+	+	+
				5	-	-	-	+	+	+	+	+
<b>ТКЖ2 (погружной)</b>												
 Т раб. (-40...+600°C)	ХК(L)	2/4	-	-	+	+	+	+	-	-	-	
		3/4	-	-	-	-	+	+	+	+	+	
<b>ТКП1 (поверхности)</b>												
 Т раб. (-40...+600°C)	ХК(L)	3	-	-	+	+	+	+	-	-	-	
<b>ТКП2 (поверхности)</b>												
	Pt100											
	ХК(L)											
	Тип	Т раб.										
Pt100	-50... 120°C											
ХК(L)	-50... 120°C											
<b>ТКП3 (поверхности)</b>												
	Pt100											
	ХК(L)											
	Тип	Т раб.										
Pt100	-50... 100(200)°C											
ХК(L)	-50... 100(200)°C											

**Термопреобразователи к измерителю температуры ИТ 5 - Т**


Рисунок, Т раб.	Тип	d, мм	l, мм										
			60	80	100	120	200	300	400	600	800		
<b>ТКК1 (контроль температуры продуктов в термокамере)</b>													
	50М	2	-	+	-	-	-	-	-	-	-		
		4	-	-	-	+	-	-	-	-	-		
	100П	4	-	-	-	+	-	-	-	-	-		
		Тип	Т раб.		d								
50М	-50... 160°C		2										
50М	-50... 160(200)°C		4										
100П	-50... 160(200)°C		4		Pt100	2	-	-	+	-	-	-	-
Pt100	-50... 160°C		2										
Pt100	-50... 160(200)°C		4		ХК(L)	2	-	-	+	-	-	-	-
ХК(L)	-40... 200°C		2; 4			4	-	-	-	+	-	-	-

**ТКК2 (контроль температуры воздуха в термокамере)**




Тип	Т раб.		4	+	-	-	-	-	-	-	-	-
50М	-50...160°C	50М	4	+	-	-	-	-	-	-	-	-
100П	-50...160(200)°C		5	-	+	-	-	-	-	-	-	-
Pt100	-50...160(200)°C	Pt100	4	-	-	-	-	-	-	-	-	-
ХК(L)	-40...200°C		5	-	+	-	-	-	-	-	-	-

**ТВЖ1 (встроенный, погружной)**




Тип	Т раб.		4	-	-	-	+	+	+	+	-	-
50М	-50...160°C	50М	4	-	-	-	+	+	+	+	-	-
100П	-50...160°C		100П	4	-	-	-	+	+	+	+	-
Pt100	-50...160°C	Pt100	4	-	-	-	+	+	+	+	-	-

**ТВЖ2 (встроенный, погружной)**




ХК(L)	3/4	-	-	-	-	+	+	+	-	-
-------	-----	---	---	---	---	---	---	---	---	---

**ТВВ1 (воздушный) – только для ИТ 5Т - 3 с разъёмом РС - 4**



50М												+	
50М	-50...50°C	Pt100											+
Pt100	-50...50°C												

**ТГ (гибкий)**



ХК(L)	3	L = 1500...6000 мм										
-------	---	--------------------	--	--	--	--	--	--	--	--	--	--